



**ALFA ROMEO tensioner**

| SKF      | BREDA  | Other No.                                   | DRAWING | PICTURE |
|----------|--------|---|---------|---------|
| VKM12101 | CR1646 | 60805833<br>5997325<br>F-220257<br>F-203093 |         |         |

**AUDI car tensioner**

| SKF  | INA                                | BREDA  | Other No.  | DRAWING | PICTURE |
|--|------------------------------------|--------|------------|---------|---------|
| VKM11000                                   | F-220093<br>F-81749.1<br>F-81749.5 | CR1680 | 026109243E |         |         |
| VKM11010<br>307839BA<br>307839EB<br>393614 | F-220095                           | CR1682 | 068109243F |         |         |





## BMW car tensioner

| SKF      | INA                    | BREDA  | Other No.   | DRAWING | PICTURE |
|----------|------------------------|--------|-------------|---------|---------|
| VKM28000 | F-211941.4<br>F-219476 | CR1849 | 11311721264 |         |         |
| VKM28001 | F-220085               | CR1850 | 11311709646 |         |         |
| VKM38004 | F-220259.2             |        | 11281748131 |         |         |
| VKM38003 | F-220090.1             |        | 11281748130 |         |         |





## DAEWOO car tensioner

| SKF      | IRB     | GMB     | Other No.                  | DRAWING | PICTURE |
|----------|---------|---------|----------------------------|---------|---------|
| VKM76102 | IR-9973 | GT30010 | 12810-81400<br>12810-81401 |         |         |

**DAIHATSU car tensioner**

| SKF      | IRB     | GMB     | Other No.   | DRAWING  | PICTURE   |
|----------|---------|---------|-------------|--|---|
| VKM77300 | IR-9038 | GT40010 | 13505-87702 |  |  |

**Ford car tensioner**

| SKF      | INA                                 | BREDA  | Other No.   | DRAWING  | PICTURE   |
|----------|-------------------------------------|--------|-------------|--|---|
| VKM11000 | F-220093<br>F-217668.2<br>F-81749.5 | CR1680 | 026109243.E |  |  |
| VKM14000 | F-82798<br>F-84666.4                | CR1694 | 1496915     |  |  |



## Ford car tensioner

| SKF      | INA                  | BREDA  | Other No.                | DRAWING | PICTURE |
|----------|----------------------|--------|--------------------------|---------|---------|
| VKM14100 | F-140057             | CR1872 | 6497120                  |         |         |
| VKM14103 | F-110937<br>F-123642 |        | 96FF-6K254-BA            |         |         |
| VKM14105 | F-140057.2           |        | 1005516                  |         |         |
| VKM14201 | F-140055<br>F-210045 |        | 6182891<br>84SM-6K254-CA |         |         |

**Ford car tensioner**

| SKF      | INA                   | Other No.                | DRAWING | PICTURE |
|----------|-----------------------|--------------------------|---------|---------|
| VKM14301 | F-140056<br>F-48559.7 | 6121753<br>CR1830        |         |         |
| VKM24100 | F-140073.2            | 1005823<br>96FF-6K254-DA |         |         |
| VKM24107 |                       | 1040677                  |         |         |
| VKM74200 |                       | B630-12-700C/D           |         |         |
| VKM74201 |                       | B660-12-730B/C           |         |         |



**Ford car tensioner**

| SKF      | Other No.                   | DRAWING | PICTURE |
|----------|-----------------------------|---------|---------|
| VKM74600 | K973-12-700<br>FEIH-12-700A |         |         |
| VKM84000 | GT80040                     |         |         |
| VKM84201 | B660-12-730A                |         |         |
| VKM84600 | FE1H-12-730A                |         |         |
| VKM84601 | FE3N-12-730                 |         |         |

**Ford car tensioner**

| SKF       | INA        | Other No.        | DRAWING | PICTURE |
|-----------|------------|------------------|---------|---------|
| VKM17406  | F-140564.1 | Rover-LHP 100680 |         |         |
| VKM23529S | F-140070.1 | Rover-LHV 100150 |         |         |
|           | F-44818.2  | F87A-6A228-AA    |         |         |





## FIAT tensioner

| SKF                                 | INA                  | BREDA  | Other No.                      | DRAWING | PICTURE |
|-------------------------------------|----------------------|--------|--------------------------------|---------|---------|
| VKM12003                            |                      | CR1667 | 4386575                        |         |         |
| VKM12010                            | F-45986              | CR1659 | 4427068                        |         |         |
| VKM12100<br>BA2B633272              |                      | CR1664 | 4385583                        |         |         |
| VKM12101<br>BA2B633624D<br>633624BC | F-220257<br>F-203093 | CR1646 | 60805833<br>5997325<br>5997326 |         |         |

**FIAT tensioner**






| SKF                                | INA                  | BREDA  | Other No.                      | DRAWING | PICTURE |
|------------------------------------|----------------------|--------|--------------------------------|---------|---------|
| VKM12200<br>441754D<br>BB1B630632B | F-36261<br>F-36261.1 | CR1654 | 5972277<br>95619217<br>0829.17 |         |         |
| VKM12380<br>BA2B633332A            | F-220323             | CR1665 | 4740846<br>5001001272          |         |         |
| VKM22151<br>BB1D630643B            |                      | CR1645 | 7553565                        |         |         |
|                                    | F-110591.1           |        | 46740726                       |         |         |



**GENERAL MOTORS tensioner**

| SKF      | INA       | BREDA  | Other No.                      | DRAWING | PICTURE |
|----------|-----------|--------|--------------------------------|---------|---------|
| VKM25202 | F-224963  | CR1880 | 09128741<br>90411787<br>636418 |         |         |
| VKM26501 | F-123142  |        | Nro.MWM38001                   |         |         |
|          | F-44818.2 |        | F87A-6A228-AA                  |         |         |

**HYUNDAI car tensioner**

| SKF      | IRB     | GMB     | Other No.   | DRAWING  | PICTURE   |
|----------|---------|---------|---|--|---|
| VKM75001 | IR-9987 | GT80090 | MD146186<br>JPU60-238+JF441   |       |    |
| VKM75004 | IR-9064 | GT10080 | PU316029BRKDV<br>24410-35000<br>24410-35020<br>24410-35060                          |       |    |
| VKM75006 | IR-9975 | GT10022 | 24410-22020<br>24410-26000<br>JPU60-283+JF485                                       |    |  |
| VKM75008 |         | GT10040 | 23357-32020<br>23357-32040<br>23357-32050<br>JPU60-243                              |   |  |
| VKM75033 | IR-9059 | GT10032 | 60TB041<br>MD011536<br>JPU60-216+JF391<br>24410-32553<br>24410-32555<br>24410-32560 |   |  |



**HYUNDAI car tensioner**

| SKF      | IRB     | GMB     | Other No.  | DRAWING | PICTURE |
|----------|---------|---------|--|---------|---------|
| VKM75044 |         | GT10070 | 23357-33120<br>23357-33130<br>JPU55-54   |         |         |
| VKM75100 | IR-9986 | GT10010 | 24410-21000<br>24410-21010<br>24410-21014<br>24410-21020<br>60TB048B01<br>JPU60-71+JF129 |         |         |
| VKM75144 | IR-9054 | GT10060 | 24450-33010<br>24450-33020<br>JPU60-215  |         |         |
| VKM75601 |         | GT10140 | 24317-42000<br>24317-42010<br>24317-42020<br>60TB039B01                                  |         |         |
| VKM75612 |         | GT10130 | 23357-42000<br>23357-42010<br>23357-42020<br>23357-42030<br>MD050125<br>JPU581+JF181     |         |         |

**HYUNDAI car tensioner**

| SKF       | IRB     | GMB     | Other No.   | DRAWING | PICTURE |
|-----------|---------|---------|---|---------|---------|
| VKM85000  | IR-9055 | GT10050 | 24810-33001<br>24810-33011<br>24810-33021<br>24810-33024<br>MD156604<br>PU276033RR14D |         |         |
| VKM23502S |         | GT10150 | 24410-23011<br>70TB0615   |         |         |
|           |         | GT10090 | 25281-35020<br>25281-35050<br>25281-35060<br>MD308882<br>PU1590-29RR1HN               |         |         |
| VKM89001  |         | GT10120 | 25281-35520<br>25281-35530<br>PU351027CRR1DY  |         |         |
| VKM85145  |         | GT10170 | 24810-26010<br>24810-26020  |         |         |



## HYUNDAI car tensioner

| SKF      | GMB     | Other No.   | DRAWING | PICTURE |
|----------|---------|---|---------|---------|
|          | GT10100 | 24450-35500<br>24450-35510<br>24450-35530<br>PU106018BRR9D  |         |         |
| VKM85002 | GT10110 | 24810-35500<br>24810-35510<br>24810-35530<br>PU305729ARR1DW |         |         |
| VKM85147 | GT10160 | 24810-23011<br>60ST624DDWAX                                 |         |         |
|          | GT10031 | 24410-32580<br>MD129033<br>60TB041B12                       |         |         |

**HOLDEN car tensioner**

| SKF      | IRB     | GMB     | Other No.                               | DRAWING | PICTURE |
|----------|---------|---------|---|---------|---------|
| VKM72000 | IR-9032 | GT80110 | 13070-01M00<br>X3-JPU60-27<br>60TB041B2 |         |         |

**HONDA car tensioner**

| SKF      | IRB     | GMB     | Other No.     | DRAWING | PICTURE |
|----------|---------|---------|---------------|---------|---------|
| VKM73000 | IR-9927 | GT80100 | 14510-PM7-003 |         |         |





## KIA car tensioner

| SKF      | GMB     | KOYO            | Other No.                                | DRAWING | PICTURE |
|----------|---------|-----------------|--|---------|---------|
| VKM74200 | GT20040 | PU245228CRR1H-1 | K151-12-700<br>B630-12-700C/D<br>IR-9983 |         |         |
| VKM74201 | GT20050 | PU285226RR1HV   | K938-12-700<br>B660-12-730B/C<br>IR-9069 |         |         |
| VKM74600 | GT20010 | PU259229RR1HV   | K973-12-700<br>52TB2802B02<br>IR-9073    |         |         |
| VKM84005 | GT20090 |                 | OJE-12-730A<br>IR-9088                   |         |         |
| VKM84006 | GT20100 |                 | OJE-12-740A<br>IR-9089                   |         |         |

**KIA car tensioner**

| SKF      | GMB     | KOYO                | Other No.                    | DRAWING   | PICTURE   |
|----------|---------|---------------------|------------------------------|---|---|
| VKM84201 | GT20060 | PU245226BRR1H       | B660-12-730A<br>OK938-12-730 |   |    |
| VKM84600 | GT20020 | DG3060312RD2HC2     | FE1H-12-730A<br>OK973-12730  |   |    |
| VKM84601 | GT20030 | DDG30602RD1HC25+SV1 | FE3N-12-730<br>OK955-12730   |  |  |



## LADA car tensioner

| SKF      | BREDA  | Other No.                                    | DRAWING | PICTURE |
|----------|--------|--|---------|---------|
| VKM18200 | CR1860 | 21051006118<br>21051006125<br>[SBR]TD-302064 |         |         |
| VKM13046 |        | 2108-1006120<br>[SBR]TD-302120               |         |         |
| VKM13044 |        | 2112-1006120                                 |         |         |
|          |        | 2112-1006135                                 |         |         |

**Mercedes-Benz car tensioner**

| SKF      | INA      | BREDA  | Other No.  | DRAWING | PICTURE |
|----------|----------|--------|------------|---------|---------|
| VKM38001 | F-219949 | CR1457 | 6012000970 |         |         |
| VKM38002 | F-220092 | CR1456 | 6012000770 |         |         |
| VKM38012 | F-220092 |        | 6012001270 |         |         |



## MITSUBISHI car tensioner

| SKF      | IRB     | GMB     | Other No.                         | DRAWING | PICTURE |
|----------|---------|---------|-----------------------------------|---------|---------|
| VKM74200 | IR-9983 | GT20040 | B630-12-700C/D<br>PU245228CRR1H-1 |         |         |
| VKM74201 | IR-9069 | GT20050 | PU285226RR1HV                     |         |         |
| VKM75001 | IR-9987 | GT80090 | JPU60-238+JF441<br>MD146186       |         |         |
| VKM75004 | IR-9064 | GT10080 | PU316029BRKDV<br>MD146578         |         |         |

**mitsubishi car tensioner**

| SKF      | IRB     | GMB     | Other No.   | DRAWING | PICTURE |
|----------|---------|---------|---|---------|---------|
| VKM75008 |         | GT10040 | 23357-32050<br>JPU60-243<br>MD128765  |         |         |
| VKM75033 | IR-9059 | GT10032 | 24410-32555<br>24410-32560<br>24410-32553<br>MD011536<br>60TB041<br>JPU60-216+JF391 |         |         |
| VKM75044 |         | GT10070 | 23357-33130<br>JPU55-54<br>MD115976   |         |         |
| VKM75100 | IR-9986 | GT10010 | 60TB048B01<br>JPU60-71+JF129<br>MD030605  |         |         |



**MITSUBISHI car tensioner**

| SKF      | IRB     | GMB     | Other No.                               | DRAWING | PICTURE |
|----------|---------|---------|---|---------|---------|
| VKM75144 | IR-9054 | GT10060 | 24450-33020<br>JPU60-215<br>MD129355    |         |         |
| VKM75601 |         | GT10140 | 60TB039B01<br>MD050135                  |         |         |
| VKM75612 |         | GT10130 | 23357-42030<br>JPU581+JF181<br>MD050125 |         |         |
| VKM85000 | IR-9055 | GT10050 | MD156604<br>PU276033RR14D               |         |         |
|          |         | GT10090 | MD308882<br>PU1590-29RR1HN              |         |         |

**MAZDA car tensioner**

| SKF      | IRB     | GMB     | Other No.   | DRAWING  | PICTURE   |
|----------|---------|---------|---|--|---|
| VKM74200 | IR-9983 | GT20040 | B630-12-700C/D/E<br>PU245228CRR1H-1                         |    |    |
| VKM74201 | IR-9069 | GT20050 | B660-12-730B/C/D<br>PU285226RR1HV                           |    |    |
| VKM74600 | IR-9073 | GT20010 | K973-12-700<br>52TB2802B02<br>PU259229RR1HV<br>FEIH-12-700A |   |  |
| VKM84000 |         | GT80040 | FS01-12-730A<br>JPU52-138                                   |  |  |





## MAZDA car tensioner

| SKF      | IRB     | GMB     | Other No.  | DRAWING | PICTURE |
|----------|---------|---------|--|---------|---------|
| VKM84005 | IR-9088 | GT20090 | JE26-12-730A   |         |         |
| VKM84006 | IR-9089 | GT20100 | JE26-12-740A<br>OJE-12-740A                                    |         |         |
| VKM84201 |         | GT20060 | B660-12-730/730C<br>B660-12-730A<br>PU245226BRR1H<br>JPU52-131 |         |         |
| VKM84600 |         | GT20020 | FE1H-12-730A<br>DG3060312RD2HC2                                |         |         |
| VKM84601 |         | GT20030 | FE3N-12-730<br>DDG30602RD1HC25+SV1                             |         |         |

**NISSAN car tensioner**

| SKF      | IRB     | GMB     | Other No.                               | DRAWING | PICTURE |
|----------|---------|---------|---|---------|---------|
| VKM72000 | IR-9032 | GT80110 | 13070-01M00<br>X3-JPU60-27<br>60TB041B2 |         |         |

**OPEL/VAUXHALL car tensioner**



| SKF      | INA     | BREDA  | Other No.                      | DRAWING | PICTURE |
|----------|---------|--------|--------------------------------|---------|---------|
| VKM15121 | 9202478 | CR1885 | 636740<br>636734<br>5636722    |         |         |
| VKM15202 | 979195  | CR1800 | 636726 ex<br>636737<br>5636738 |         |         |
| VKM15402 | 979311  |        | 5636429                        |         |         |









**OPEL/VAUXHALL car tensioner**

| SKF      | INA                  | BREDA  | Other No.           | DRAWING | PICTURE |
|----------|----------------------|--------|---------------------|---------|---------|
| VKM25200 | F-200242<br>F-220135 | CR1696 | 636421<br>QTT165    |         |         |
| VKM25201 | F-220086             | CR1837 | 636422<br>QTT166    |         |         |
| VKM25202 | F-224963             | CR1880 | 636737<br>636418    |         |         |
| VKM25208 |                      |        | 636730<br>NTN6004LU |         |         |
| VKM25212 | F-224964             | CR1801 | 636415<br>5636425   |         |         |

**OPEL/VAUXHALL car tensioner**

| SKF      | INA      | BREDA | Other No. | DRAWING  | PICTURE   |
|----------|----------|-------|-----------|--|---|
| VKM25500 | F-224936 |       | 5636424   |  |  |

**OTHER car tensioner**

| SKF      | Other No.   | application   | DRAWING  | PICTURE   |
|----------|---|---|--|---|
| VKM74501 | 1257120<br>IR-9071<br>52TB057B01<br>52TB0532B01               | [FORD]<br>Ttelstar 1.6/1.8/2.0<br>[MAZDA]626/929<br>Luce 1.6/1.8/2.0<br>Ccosmos<br>[BONGO]1.8 |   |   |
| VKM75006 | 24410-21010<br>B660-12-730B/C<br>IR-9061<br>[GMB]<br>E6203RTA | [HYUNDAI]<br>Accent<br>Pony<br>Scoupe   |  |  |
| VKM13244 | 0829.60<br>F-13244  | [CITROEN]<br>Berlingo<br>Evasion<br>Jumpy<br>XantiaA<br>Xsara                                 |  |  |



**SUZUKI car tensioner**

| SKF      | NTN             | IRB     | GMB     | Other No.   | DRAWING | PICTURE |
|----------|-----------------|---------|---------|-------------|---------|---------|
| VKM76102 | JPU42-17+JF417  | IR-9973 | GT30010 | 12810-81401 |         |         |
| VKM76103 | JPU52-128+JF434 | IR-9017 | GT80080 | 12810-73002 |         |         |
|          | JPU52-111+JF434 |         | GT80120 | 12810-53A00 |         |         |

**RENAULT car tensioner**

| SKF      | INA                    | BREDA  | Other No.                         | DRAWING | PICTURE |
|----------|------------------------|--------|-----------------------------------|---------|---------|
| VKM16000 | F-39924.10<br>F-123958 |        | 7700736085                        |         |         |
| VKM16101 | F-39508.5<br>F-123776  | CR1838 | 3343740-1<br>7700726440<br>QTT112 |         |         |
| VKM26114 | F-123777<br>C751       |        | 7700107249<br>7700875307          |         |         |



## SEAT car tensioner

| SKF      | INA                 | BREDA  | Other No.                       | DRAWING | PICTURE |
|----------|---------------------|--------|---------------------------------|---------|---------|
| VKM11000 | F-220093            | CR1680 | 026109243E<br>TB8328<br>G780070 |         |         |
| VKM11010 | F-220095<br>F-87936 | CR1682 | 068109243F                      |         |         |

**TOYOTA car tensioner**

| SKF      | IRB     | GMB     | Other No.                               | DRAWING | PICTURE |
|----------|---------|---------|---|---------|---------|
| VKM71003 | IR-9992 | GT80020 | 13505-74020<br>57TB3705B01<br>PU385827  |         |         |
| VKM75004 | IR-9064 | GT10080 | MD104578<br>PU316029BRLDV               |         |         |
| VKM71007 | IR-9999 | GT80010 | 13505-15040/41                          |         |         |
| VKM81004 | IR-9991 | GT80030 | 13503-63021<br>57TB3701<br>PU355816RR9H |         |         |













**VOLVO tensioner**

| SKF      | INA                   | Q.H.   | BREDA  | Other No. | DRAWING | PICTURE |
|----------|-----------------------|--------|--------|-----------|---------|---------|
| VKM16101 | F-39508.5<br>F-123776 | QTT112 | CR1838 | 3343740.1 |         |         |
| VKM21031 | F-220096<br>F-85300.2 | QTT174 | CR1681 | 1257120   |         |         |

**VOLKSWAGEN car tensioner**







| SKF      | INA  | BREDA  | Other No.                                   | DRAWING  | PICTURE   |
|----------|--|--------|---|--|---|
| VKM11000 | F-220093<br>F-81749.1<br>F-81749.5<br>F-217668.2 | CR1680 | 026109243 E<br>GT80070<br>IR-9805<br>QTT127 |    |    |
| VKM11010 | F-220095<br>F-87936                              | CR1682 | 068109243 F<br>QTT172<br>GT80280            |   |   |
| VKM31004 |  |        | 028145278 E                                 |  |  |
| VKM31007 | F-231228   |        | 074145278 E                                 |  |  |





**VOLKSWAGEN car tensioner**

| SKF | INA      | BREDA | Other No.   | DRAWING | PICTURE |
|-----|----------|-------|-------------|---------|---------|
|     | F-214797 |       | 028145278 E |         |         |
|     | F-220288 |       | 046130195 B |         |         |
|     | F-231222 |       | 053903341   |         |         |

**PROTON car tensioner**

| SKF      | NTN             | IRB     | GMB     | Other No.              | DRAWING   | PICTURE   |
|----------|-----------------|---------|---------|------------------------|---|---|
| VKM75100 | JPU60-71+JF129  | IR-9986 | GT10010 | MD030605<br>60TB048B01 |   |    |
| VKM75001 | JPU60-238+JF441 | IR-9987 | GT80090 | MD146186               |   |    |
| VKM75033 | JPU60-216+JF391 | IR-9059 | GT10032 | MD011536<br>60TB041    |  |  |

**PORSCHE car tensioner**

| SKF      | INA  | IRB     | GMB     | Other No.  | DRAWING  | PICTURE   |
|----------|--|---------|---------|------------|--|---|
| VKM11000 | F-217668.2<br>F-220093<br>F-81749.1<br>F-81749.5 | IR-9805 | GT80070 | 026109243E |  |  |